

Annexure D

BUILDING SAFETY CERTIFICATE

No. 068

Dated: 26/02/2025

It is certified that the existing building **Guidance International School** (name of the building or premises) at Gokulpur, Jakara, Khordha, Odisha (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground Floor † 1	Ground Floor † 1	—	—	—	—

The building is owned/occupied by **Guidance International school** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **R & B Sub- Division ,Begunia** (Name of Department/Govt.) on **11/02/2025** (date of inspection) in the presence of **Mr.Syed Inzamamul Haque**, Bhubaneswar (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **26/02/2025** for a period of **03** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Roof top should be clean in every one year
2. Painting to the building to be done in every 3 years
3. Fire safety norms to be applied as per the guidelines.

Issued on 26/02/2025 at Gokulpur by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Dibaker Swain
26.02.25
Asst. Executive Engineer
R & B Sub-Division
Begunia
Asst. Executive Engineer
R & B Sub- Division
Begunia